Today I replaced the exhaust manifold. And guess what I found, the water leak that was supposedly a bad radiator cap was really a cracked block. The crack runs horizontally between two soft plugs hidden from view by the intake and exhaust manifolds. While working on the engine I noticed that the value cover bolt on the ream of the value cover, next to the firewall was cross threaded and only in about two threads. I realize that is is an extremely hard bolt to get to, the fact that the value cover won't come off without moving the engine makes it even more difficult, but that is why I chose to have "experienced" APIC mechanics work on it.

Before you assume I haven't kept anti-freeze in it, I own 4 other cars, do all of my own maintainence work, own an anti-freeze tester and keep the freeze point at at least 20 degrees below zero (the coldest it has been in the ten years we have lived in Oregon was 4 degrees in January of 1979). I am quite sure this crack has been there for a long time.

I will admit that the Eagle is a great concept, and the car runs great when there is snow or ice on the ground. But for a car that has not been off-roaded, or abused we have had more than our share of problems than deserved for only 87,000 miles. One of my other cars is a 1970 Ford station wagon we bought new in 1970, it currently has 187,000 miles on it; the engine has never been opened up, it leaks a little from the automatic, but much, much less than the Eagle.

hy complaints about the dealer could go on, like the rattle in the door they couldn't find. I finally got so fed up with it I removed the door panel and found a 4' diameter piece of sheet metal laying in the bottom of the door. But according to Lilliagnd's there was nothing wrong.

It seems to me if APC is going to stay in business they must satisfy their customers, but the way your dealers are going about it is not getting the job done. I don't mind paying a fair price for a job well done, but I have never felt your mechanics know what they are doing.

I have only one request: What, if anything, will AMC do to help me with the cracked block? I realize the car is well out of warranty, but I am sure that the crack was there long before the warranty ran out. I am also aware that many times a car is covered by "hidden waranties" are there any such programs to help out in a situation like this?

Respectfully

John L. Sailors 1876 NE Thomas Hillsboro, OR 97124

CUC 857

620 Second Street Boone, Iowa 50036 February 7, 1983

American Motors Sales Corporation Owner Relations Department 14250 Plymouth Road Detroit, Michigan 49232

Dear Sir.

On December 18, 1979 I purchased a 1980 Eagle, VIN # A0C365C181965. The dealer involved was Edwards Lincoln-Mercury-AMC. Inc. of Council Bluffs, Iowa. The dealership was most helpful in all the problems that I had with this car. Now howeverthe dealership has closed and my problems are still continuing. One positive note about this car is that it truely is a fine road car that I have enjoyed driving.

But alas, now comes my long tale of woe that has motivated this letter. As I write this please remember that I am a layman and the terms may not be "correct". The initial problems started a few miles after I drove off the lot. There was no heat, the front wheel assembly made a rather strange noise, (my car was in the dealer's shop for a month for this problem) windows were out of the tracks, doors out of alignment, air conditioning problems, cruise control problems, fog lamps failed, the trailer package wiring was never hooked up, the valve cover leakes oil all over the engine and causes billows of smoke, the trunk leaks and the tires(not yourfault) are terrible.

So armed with myfaith in AMC and my 36 month/36,000 mile Service Secrity Flan I went to get these problems repaired. Many of them were fixed under the "adjustment/breaking in phase" during the initial 12,000 mile plan now is really a 24,000/24 month "deal" is it not?

So after the problems repeated themselves I decided that I would really be secure with your plan of Service security. This has proven to be false. The Ron Willey Dealership of Nevada, Iowa (nearest one) sells and services AMC. I told them my problems and they forged ahead to help with my problems. While my car was being taken apart the Service Security plan was discovered to be rather unsecure. Ron who really is a nice fellow said that he would investigate


Gentlemen, I am outraged! My problems are still with me and I feel that it is your responsibility to repair the heat, terrible oil leak, and the reoccuring problems that have never been resolved. I was told that this may cost several hundred dollors and that it wid be at my expense. I refused to take that gamble. They put

my car together and I paid the bill.

I hope that the friendly folks at AMC will review this problem and offer some solution that would be acceptable to all parties concerned.

> Optimistically your Daniel B. Bagle

1000 CTS TORGOLDE	12479 44 105 105 105 105 105 105 105 105 105 105	To 22-11	. Dot you deal with easy owner taxes in serms of poolemeelpor lakestard fired of autotacion (notation any absolute taxes are associated for your deal with easy of the control of the cont	Manne Manne Company A Wool (min by consult in the consult of the	I dissuiffed orestal, complete back of report and make a copy for sone life. Zone Sign ret—"X"-Cax" Require Fined Ser "ce lakeager Segust" As epited	
1 Hersellh	10 10 10 10 10 10 10 10 10 10 10 10 10 1	Liberation of the distribution of the control of th		ON Contractions.	OPP AND WHEN DEPORT	



C: MAIL

7 East Market Street Burgettstown, Pa. 15021 May 25, 1983

0110

President of American Motors American Motors Corporation 1h250 Plymouth Rd. Detriot Michigan h8232

Dear Sire

I am writing to you concerning my repeated attempts to heave my 1961. Eggle repaired. I purchased the car in August 67 1981 at "#Relonald AMC." Relonald, Pa. I had no trouble with service there: They sade several attempts to fix the cil leak from July of 1982 to the time their delerning burned down. In fact, I had an appointment to have the cil leak repaired the day after the fire. I didn't know where to take the car for warranty repairs of the leak after that; so I wrote to the Zone Manager and I am enclosing a cory of the letter I received from them.

On receipt of this letter. I called Mr. Rezered; and received an appointment with the sales representative for February 28th. ath Vasko's in Ganonsburg, Pa. I was instructed to call Vasko's a few days ahead of time which I did. When I called -- Vasko's knew nothing about a service representative coming to their dealership; could I call back the next day. The next day they told me to be there at 9:30am on the 28th. When I got there-no representative showed up, so Vasko's called the Warrendale office and was told the representative couldn't make it that day to look at the car but for them (Vasko's) to look at it and fix it. They replaced the valve head cover and said it was fixed. It leaked that day when I got home-the next day I called and they said to wait a counle weeks because it might be old oil. I was then hospitalized for two weeks so I wasn't able to get the car back to Vasko's until April 18th. That day they replaced the oil pan and seal and said it was fixed. It leaked that day when I got home and everyday since. I took the car back today and when I went to pick it up. Vasko's told me that the Warrendale office refused to cover the repairs under warranty because they already paid to repair two leaks and wouldn't pay for the third. I say you didn't pay to fix two leaks, you paid for two attempts to fix the same leak. The amount of oil that leaked from my car has not waried at anytime since they started to repair it. In other words, the leak was never fixed the first time.

Today I was charged \$81.62 for repairs for a leak that I had since July of 1982. I have made three trips to my original dealership "McDonald AMC"—which burned down and three trips to Vasko's a distance of hio miles roundtrip, lost a days work to meet a service representative who didn't show. All I want from you is my881.62 and my repairs covered under warranty until the leak is fixed.

I talked to the Owner Relations Department today and they wanted a copy of the Service Record for the car. I don't have a copy because the "Relocald ANC" burned down. Any repairs I had done, I merely signed that they were completed.

If you wish to speak to me about this matter, you can reach me at the above address or at 112-917-5105 after 11000 m anyday.

Thank you,


1 1 1 1 1 1 1 1 19 15 11 19

Many Mangaret Familie Mary Margaret Fernili

2 Enclosures

1981 American Eagle Kamback & cylinder 1-ACBK5605BK205522

WEEF.




nows 100 pus Johnstown Partition Purk January (San Jan american Motors Corporation Pa Box 442 Detrut Muchegan 48232 Dear Sno. lit the and of 1983 I lought my wife at 1985 X4 lagle. Limited Edition, and now I regret my decision Ever since I purchased it There had endless problems with it I will refer to incidents within the fast Oil Irahs have always been a peoblem. I find it impeterous to vesel someone with a new parment due Last spring my wife made a trip to Cleveland ahir. other she begon "home she broke down on the Europeke the can wouldn't start In order for her to return I had to sail off work, rent a U-Haul and make a true to Clintond I apent were serve on the true and show calle trying to find an a m C Medershipe that had a cril not one of them had one Smight add that not one of your specially trained technicians informed me or even suggested that a G.M. coil would also work in an W.M.C. I found this out I... accident I think I might here another name for these people other than factory trained technicaling

Most ricently the starter went out of took to the garage for repair, it landed up meding a o fly wheel , clutch , and presence plate . when I picked the car up it had a vibration that you fould feel an the whole can I returned the ear to find out what the virbation was because it wasn't there when I took it in for the pterter Theythen rebuilt the near differential twice I hen they said a laffel in the muffler was broke I replaced the muffler Sonight add this muffler was replaced Swhim the car was a wuple of months old belause it rusted out these are only a few of the problems I have had with this car I assure you there were my others. Most of the repair have been enreed by warrenty and insurance I have had to pay for a slave expender and mader hydraulic expender, a evel and electronic ignition lop, clutch, pressure plate, muffler surpe test le new that is only a year old should not have had to have all this repair meeded.

My per is back in the garage because it still has the surbection, the oil leaks and I am not petting a smoothe pull out on the clutch Also the super test showed a bost and when is being filed.

I wont dany the fact that an bagk we not in good law I foun a 1982 5×4 Eagle that has 55.000 miles on it that are almost trouble free I am & very pleased with its performance, but the? 1983

fe has proved to be a lemon as far as I . see I am thousally discusted with it being , and out of the sepain shop I did not buy a new ear for my wife for it to be in a repair shop all the time I did call Natroct to no avail. They didn't seen want my mame. I feel this is no way to run I business like a M. C. They expersed me to the Pettaburg Decision and I've called there endlessly and the line is always busy. I trud to get the name of the president of a M. C and no one seems to know here mome I find that very odd that no one knows who Beads the company they are representing and working I feel if the president knew of the problems of The ear I'm sure he wouldn't want this par to Represent american Workmanship and he'd want to do something to make it right. I have contacted the Better Business Liveau for advice I also will contact a lawyer if advised I don't feel I proud have to put up with this car any longer. Lespectfully John & Maldet



February 13,1982 Orietire acru 39 State a. Dr. apt. 11 Creektowaga Mew York Dear Lies I have always been pleased with your automobiles This can had been our second american motor purchase. I find had a 1976 Matallar & now we own a 1980 Spirit We have had a problem cute the April, for one of the coolse Cour gasked has been replaced the times within the first year we owned the can and now ist has been replaced again, We purchased the can ad Steridan amend motor which has receptly closed at the and of this past year (1981) to now be hourto tale the can for repairs and Wheledy Oldha Ican understand why they couldn't back the goodest, because they were not the look to replace it. But mis main problem is the

another we had been loving to the with our nextu, so I took the canto Holiday Olds. Well one of the men looked at the can and said consetting remove the hood was had as the heady was surking in the our was not coming in through to be inside of the case to I made an appointmed to being the course furthe value come goods to be explaced of Can and paying them \$55.51 for these wach, Luco driving home and again the hed was not coming into the can They replace the trumented trad day, but that really wasn't medicary turned night around and went hack to the dealer, New he told me the header needed a new switch, which bey had to order, so I had to want a wel. without no head in the can I I paid fathe past and they said thee would here labor charge because the can was not bud properly the first time I returned about a week late and they told mette trong paid had been reduced, son they

re-ordered the different evited, so thank tolucid about another week, Well, I went book again, the switch was per in ord mo Isba charge I west I took the can hime bu a few clays and again the con heater was acting the same way to I returned to the dealer ence again Nawthey re-placed another Switch for 14, 93 which they replaced at their expense again I had the con home for two deep and the heate was not coming in the can properly again, as for a 5th time Ireturned back to the dealer about to blow my mind, in y husband deapped the can off at 10:00Am on Geo. 9, 1982 and we left the can annight for repair again which wer soo elypposed to he done od no charge. We never got the can back until around 6 00 PM on Get. 10/912 because they said they didn't have time to last at it the day of the 9th So finally after 5 trips backs fath to their dealer the heater no work properly. The only thing to they slapped

another hill on me for \$9.92, which I definitely feel I sisuld not pay because they the car was never fixed people wintel the can mosthere 5 tomes If another dealer is selling american Motor cass they should have michanic the know about there product the last trime the con was in the service manager tald my husband that a piece of insulation was blacking off-the head to the con Theofore all the head remained under the hoods I definitely feel that I should he telmbured tre 5992 for the last report that me done in the can because previous I paid \$5.5) fute same repairs, Its not my bould they could not sun to find such an easy problem as insulation blocking the lest from coming into the com My husband 4D are looking for

another can apend can but I am very leave about purchasing another asks. because of this currenessay ordered I

had to go trough This was reduculous hours to take a can back 5 times and no one could find and the problem. I would appreciate a reply, 40 an definitely plenning on hearing from you, I really ful I should be rumbered the second labor charge of 59, 92, becauselle can should of been properly fixed the Thank you and I hope to hear from you as soin as possible of I hope you feel that I am right ahour getting my second charge rumbured to me. Enclosed an Carbon copies of all the hills. Thank you again, Chustire acclu

American Motors Sales Corporation I am having a service broblem that I ale you can correct for me. of your dealer's here in Phila. Pan R. Lot AMC" replaced a faulty value_ AMC Shrit sip aglinder engine, and would not honor my service security plane for this one particular repair Therough he told mb (Mr. Fults) that in the hast. AMC refused to reimburse him. therefore, he refuses to honor the service selevity blan for this one particular repair how, therefore, I had to pay the bealer the entire costs for this repair work. The dealer told me that the plan does cover this repair, for it is frinted on the plan + does state, "gashet-cylinder head cover, but be fust can't honor the blan because Ah C's refusal to reimburse him

So I'm writing to you for the reinbursement my costs that I led to pay to the Lealer, minus \$ 25.00 of course, which is a Protection agency here. don't really want to, but I will of I have I've enclosed a copy of the bill for you to 1,50

13

If you feel that the wrong type of gasket was replaced on my car don't forget, there are two types of gaskets that can be used on my particular value cover, and AMC is the one who brull this engine, not me, so if it's made to secure either the what difference does it really make which one is used. I close the cork type of graket, but if you don't want to reimburse me Lot the Roots, don't forget about the labor costs, for I'm sure the labor is still the some, so at the lead, reinburge me for the labor costs. Thank you for your June.

Chorles B. Keely 4520"D" Street Phila., Pa 19120

#F17 #3

JAMES SEBAICE:

April 7, 1986

Zone Dealer #42-2851 Make of cer; 1980 AMC Spirit DL, 2dr Liftback Vehicle ID #ADA435C291555 Zone order #373411

Originally purchased: Sheridan Amberst Notor Sales, Inc 3900 Sheridan Drive Buffalo, New York 14226

Service since 3/86: Nolidey Olds 4811 Tremsit Road Utiliamsville, New York 14221 716-631-8780 (Service 631-8600)

"Both service writers representing the "Green Team"

Zone Dealer Code unknown
Gnril Naneper Jack Well and
Assit Service Naneper Tom Fischer
Service Writers Kathy Plevijanich
Renee Misiol Date serviced 03/08/86
Renee Misiol
Date serviced 03/08/86

"Car todrig power while in motion periodically. Disclod with tocal gas station; 20/20/56, had gas filter replaced. 00/21/56, how-up replaced pr valve, plugs.

Performance not improved. Node an appointment with AAA for Dispressic test 00/6/56, results: idle mixture too rich, check fuel filter (pasp), reself oil leads.

Perforence petting sorrer; made an appointment with its lidey Olds 057/07/25 to have a 17-point check done (card reserved in the mail good until 03/15/86), old change-requested they check to see sky the oil was leaking and told then about the loss of power while driving. Also there was a rattle under the car. And so ary trouble began,

Appointment for 8:00 a.m. US/OR/66..had to usit for the car. Approximately 1000 a.m. I use told of Kathy Newljainch that her team found the oil Leak to be caused by the valvey gasket needing to be replaced. That the leaking of oil uses state the cause of my car locating power, the foll use slought the engine. Also the pips from the suffler to converter needs to be replaced because it has rotted out due to user. I sead off there are any problems with the faul fifter or pusps as I use told by AAA. Eathys reply, No, those teats are not always 1000 true. They do their one chacks show there is a problem. These problems could be resedy by 12:00-12:30. I gave them the chi, having put no confidence in the secturior.

After being there from 8:00 a.m.-1:00 p.m. I left thinking all was well. Was it my imagination?? Is that a different rattle under my car?? Why is the car losing power STILL as I drive homm???!!!

Called Holidey Olds on Tuesday 03/11/86, having noticed all STILL leaking car losing power STILL and a NEW rattle under the car. Spoke to Renee Hiziel



at Maliday Alds complaining about all the unch does as terroring fabricular improperly) and that I don't understand shut I had noted the \$200 82 does Another appointment was set up for Herbestov (13/12/86 so they can check out the car ACATH now thinking the problem picks he in the embuscase. I decided to drop the car off at 8:00 a.m. (not being able to take time off from my light and pick it an after unch SS-00 o m. nivien than an I shought ample time to find and remain any FIRTHFR problems. Uniting for a call accord lunch time as promised by Renee Miziel ... no call came so I called at 1:00 n.m. Rence told me the mechanic (Jimmy) was still working on my car and was not sure of the problem at this time and since he was also coing to lunch that the would not back to se. Howish then received a call from her at accessions also 2:00 n.m. It was decided that the corbustator needed to be rebuilt. The mixture is running too rich (as indicated on the AAA Discressic test that they wanted no part of) due to a build up of fuel. This ich will take approximately 3, 3-1/2 hours and also the valve pasket needs to be replaced ACAIN which will take another hour. The noted that the value cover use tightened too much causing the gasker to be desced, thus my oil leak. The exhaust nine was not aligned and fastened properly causing the rattle under the car. In other words ALL the work I sat through on Saturday 03/08/86. labor charge of \$141.95 was for MOTHING!! Everything had to be redone on 03/12/86

Summery of charges from Holiday Olds;

03/08/86 Labor 141.95 Parts 41.35 Oil 4.50 Tax 15.02

TOTAL 202.82 Cer in et 8:00 a.m. out et 1:00 p.m.

03/12/86 Labor 104.00 Parts 11.73 Tax 9.26

TOTAL 124,99 Car in at 8:00 a.m. out at 10:15 p.m.

SULTINGS. Care performing better but now the maffler is about to fail off. Also motived scales casing from a pipe under the diverse's asst. The pipe installed by Noticey Dids. That evening I called Noticey Dids and spoke to Early Plantish complaining AGAIN about all the work done, or should I say NOT done. I subset if I could bring the car in and have the maffler restricted to the pipe they MEDED to replace. At no charge of course. Her reply use I should come in SUTINGS at 423 with ay two recypts and if the problem is because of counting they did, there will be no char-a-otherwise they will make any necessary repairs at of course additional costs to

CUTATOR. Called Relidary Olds at 19:00 a.m. requesting to speak to the Service Nameyor. Nerfor spealanted ALL the work dome and sy diseast farfection with the the service I had received, I desimated they fix whatever they fill not connect to the property of the service I had received, I desimated they fix whatever they fill not connect to bring the car in one y Lunch hour and they would put the car on the lift and see what the problem is an disse are yn recessary reports. I saked if the uses sure this could be done in an hour's time or I would take the efferment off, not



a

hour at 12:00 and we'll take a look.

After standing there for 30 sinutes Tom Fisher, Asart sarvice Namaper, took on back to show set the problems while my car was still some the first sinute of the indicated that the place they replaced was not fitting properly in my old mariler and I would have to pet on more. I told this that there after anything error gift my sufficer and the problem assess to be with the pipe TRY replaced. The only thing they marile and the problem assess to be with the pipe TRY replaced. The only thing they might say to be the tipe pipe and pound it down in an attempt to force it to fit the mariler. Mayon if the right part was installed this would not have to be the mariler. Mayon if the right part was installed this would not have

Problem 82...! was told I have an cil leak. I can't believe 'tryl! That's shy! brought the car in or '37/03/86. Where is the cil coming from and hashi't it been repaired on my two previous tripp? The only was to tell anything is to set up another appointment and they would have to check it out. MAM YMMAY THESE MEXT IS OTREMON THATES HOST IS OTREMON THATES.

It seems if you want to be a mechanic at Molfday Olds there is NO DOPRIENCE MECESSARY and it is strictly on the job training on the customerie car, at the the customerie sepanse and if they're Lucky they will satisfy the customerie needs...if not, just schedule another appointment and they will try again.

Saling outce fed up with the service at Holiday Dida and still leaking Dil, I sumt elsewhere to have my can serviced. Attached is a Bill from Dutroma's Auto Repair Service totalling \$130.59. As you can see from the receipt, they needed to replace the entire valve consider and geabet with sealer. The did valve cover which I have is disapped by stall Pools like someone pounding on it with a hammer or asserting, possibly to make I; fift? The Idle also had to be readjusted as I tua not after the carbarator repairs.

As a result of all this aggrevation I feel it only fair that I be relatured the outside bill of \$75..59 and at least 50% of the labor not done at the dealer.

è

Sincerely

Sudith Symm Fley chall


Judith Lynn Krefchak
1008 Lowlory Street
Buffalo, Bur York
14206

716-895-2536

Rund Hygnes Donna Infantino / American Motors

JAN 25 1984.


Page 1



It is something that people have done since the beginning of time Consumers use this valuable and viable tool to spread the word about the pros and cons of a



Yes, talking. WORD OF MOUTH is still one of the most effective and powerful forms of advertising. And today, the consumer's voice can be broadcast even further through the MEDIA.



Donna Infantino 34 Sachem Road Stony Creek, CT 06405 (203) 481-5134

January 20, 1984

W. P. Tippett, Chairman American Motors Corporation 14250 Plymouth Road Detroit, Michigan 48232

Dear Mr. Tippett:

It is only fair that a consumer first inform the manufacturer when one of their products falls far below acceptable standards and allow the manufacturer to respond, before taking other measures to rectify the situation. Please keep this statement and the message related in the cartoon in mind while reading the following account.

At one time I considered American Motors vehicles to have a good reliability and high integrity record. I have owned two American Ramblers in the past that operated quite efficiently. And, the service at Al Mac Motors of Branford, Connecticut was good. For these reasons, I felt that buying a new ARC vehicle would be a sound investment. Unfortunately, it was one of the biggest mistakes I could have made. I have been paying for it ever since in dollars, time and aggravation:

On September 18, 1979, I purchased a 1980 American Motors Spirit DL, two-door liftback with automatic transmission. During the first 5000 miles in cold, damp or rainy weather, the car would stall at slow speeds (5 m.p.h. to 25 m.p.h.) and upon stopping. This condition was reported to Al Mac Motors when it was brought in for the first maintenance check at 4,907 miles. At that time the mechanic wiped off the distributor cap (Invoice Rill52) Subsequently, the car malfunctioned in this respect intermittently.

On August 19, 1982, I brought my car in for the 22,500 mile maintenance check. I reported that there was oil all over the engine. To remedy this, the mechanic torqued down the dome cover. I also indicated that the area around the tail light was starting to rust. I told Al Maculaitis (owner of Al Mac Motors) that I thought that this condition to be unusual since the car was only two years old. He said that it wasn't unusual. To remedy the rust condition, the spots were touched up. I stated that just touching up the spots on the surface without sanding the areas first would not take care of the problem and that the rust would eat through the paint. He said that the touch up would take care of it. At the present time rust has eaten through the lower portion of the right tail light and has s'arted eating through the lower portion of the left tail light (35,387 miles) three years old) (Invoice R14789)

In retrospect, these were the least of my problems. On January 11, 1983 (26,374 miles), I brought my car into Al Mac Motors because it was running very roughly and bucking. It was stalling while being warmed up, while running at speeds between 10 m.p.h. and 35 m.p.h. and at every stop. To prevent it from stalling I had to brake with my left foot and keep the engine reving a bit with my right foot. I instructed Wayne Maculaitis to do everything necessary to remedy the problem in order to have my car operate properly.

Upon inspection, the mechanic found that the oil level was bordering on empty (at 33,021 miles a complete oil change was done - Invoice R14789). The PCV valve had become clogged causing oil to be pumped into the carburator. The mechanic also discovered that torquing down the dome cover had not remedied oil leaking onto the engine. At this time the head cover gasket was replaced (Invoice R15633)

Kindly refer to ITEM I - REPORT TO MOTOR VEHICLES DEPARTMENT OF CONNECTICUT



ITEM I: REPORT TO MOTOR VEHICLES DEPARTMENT OF CONNECTICUT

Complainant: Donna Infantino

March 8, 1983

Repair Shop: Al Mac Motors, Inc.

COMPLAINT SUMMARY:

1/11/83 - brought car into Al Mac Motors because of problem outlined under Section C - Repairs (Refer to ITEM II)

> problem diagnosed - a clogged PCV valve was pumping oil into carburator. A new PCV valve and filters were replaced (Invoice R15633)

Subsequent visit to Al Mac Motors, Inc. (about 12 weeks later)

car still stalling intermittently when I would slow down or come to a stop and was running a little roughly even after car was warmed up sufficiently.

Wayne Maculaitis and mechanic diagnosed the problem as the choke sticking. He (mechanic) sprayed the choke with a cleaner and I was told that that should remedy the problem.

Third visit to Al Mac Motors, Inc. - approximately 13 to 2 weeks after second visit

same problem still existing. Wayne Maculaitis and mechanic thought that by adjusting the idle that the problem should be rectified.

2/28/83 - Fourth visit to Al Mac Motors, Inc.

car not only still stalling intermittently, but stalling while warming up. original problem that existed prior to January 11, 1983, supposedly remedied on 1/11/83 and/or on subsequent visits, still existed.

brought car in; wrote a note in detail describing the problem and outlined all visits to Al Mac Motors. Inc. and stated that since this very same problem that existed when I brought the car in on 1/11/83 was not remedied then nor after two subsequent visits, I did not expect to be charged and would not pay to have the problem remedied on this visit.



ITEM I. REPORT TO MOTOR VEHICLES DEPARTMENT OF CONNECTICUT - Page 2

Complaint Summary cont'd.

When I called to get my car (talked to Fred, a mechanic at Al Mac Motors), I was told that a minor tune-up was done. When I reiterated my position, I was told that this work had not been authorized on any previous visits and that since this was additional work, they would have to charge me. I explained that specific authorization was given by me to remedy the problem (1/11/83), that it had in fact not been remedied at that time nor on two subsequent visits, and that on this, my fourth visit, I made a written statement to them that I wanted the problem corrected and that I would not pay for whatever had to be done. I further stated that I had lost many valuable hours and had been thoroughly inconvenienced by this whole matter.

Because our conversation was becoming a roumi-robin affair, I asked to speak to the owner, Al Maculaitis. I was connected to Wayne Maculaitis. After covering the same ground with Wayne Maculaitis and after firmly stating that I had no intentions of paying the bill, he retorted, "Well, if you feel that way!" I said thank-you and we hung up.

I went to the service desk to ask for a copy of the bill for my records. I first talked to Fred. He had not been briefed as to the outcome of Mayne's and my conversation and so expected that I would be paying the bill. He again argued his position. After stating that I refused to go ever the whole thing again, I asked to speak to Al Maculaitis. Fred called Wayne to the desk. After again having to state that I refused to pay and again requesting a copy of the bill, Wayne stated that since I refused to pay, he refused to give me the bill. He further stated that since no work was done on the car, there was no bill (This was not true because Fred had shown me the bill upon entering the garage; it indicated that a minor tune-up had been done at a cost of around \$25,00 to \$30.00).

March 3, 1983 - Complainant calls Al Maculaitis

In response to my asking if he was aware of the problem at hand, Al Maculaitis stated that he was. He said that only certain repairs were done on my car in January (Invoice R1563) because I always complained about having to spend money and that I was always giving them problems. He maintained that the car probably needed a major tune-up and that since I had never

ITEM I: REPORT TO MOTOR VEHICLES DEPARTMENT OF CONNECTICUT

Complaint Summary cont'd.

authorized one, it wasn't done. I told him that I had specifically stated to Wayne (Maculatius) that I wanted any necessary repairs to be done in order that my car run properly (1/11/83) All Maculatis then stated that he had written off the bill, that he didn't need my money and so what was the problem. I told him that the car was still not operating properly and that the same problem still existed. He reiterated that the car probably needed a major tune-up. I again stated that anything that the car needed in service and/or repairs was authorized by me on January II, 1983. I further stated that the repairs should have been done then or at least suggested to me during the two subsequent visits (subsequent visit #1 - holke sprayed with a cleaner; subsequent visit #2 - idle adjusted) and that I was not going to pit out one more dime into something that should have been remedied before now. At that point he remarked that the problem was my attitude. I informed him that my only recourse was to contact the Motor Vehicle Department. He countered with. "See, it's your attitude."

On April 15, 1983, in response to my complaint, Inspector Hatch of the Connecticut Motor Vehicles Department told me that since Al Mac Motors had attempted to remedy the problem for the least amount of expense and that since the PCV valve was not defective, they were not at fault. He further stated that he would again call Al Mac Motors to see if they were willing to bring in a manufacturer's representative to inspect the vehicle.

Inspector Hatch called back and asked me if I had tried using dry gas with a full tank of gas. I told him that I had been using dry gas with a full tank of <u>super unleaded</u> gas on a regular basis even though Wayne's instructions were only to use dry gas (1/11/83).

At that point in the conversation, he gave me the name of a factory representative (Frank Quinn, Elmsford, New York) and suggested that I call Al Mac Motors and make an appointment with them to have the car inspected by the representative. I stated that I would have no further dealings with Al Maculaitis or Al Mac Motors. Inspector Hatch said that there was nothing more that he could do, that he'd have to close my case and that should I have any further problems my case would be on file (Case #1029-83; telephone number 203 566-2433).

Subsequently, Al Maculaitis called my father and informed him that the Motor Vehicles Department could find nothing wrong with the car. When my father confronted him with the fact that the car was still not operating properly, Mr. Maculaitis stated that my car had never had a tune-up. My father argued the point as I had done but to no avail.

Having reached the point of exasperation, I continued to drive the car as it was. Although it still was not running properly, it did not exhibit the malfunction to the extent that it had from January until the March visit at which time the minor tune-up was done.

On July 13, 1983, I brought my car to Branford Exxon. It had again reached the degree of malfunction present in January, 1983. In addition, a new condition surfaced just prior to the July 13th visit. Iiquid was leaking from the heater area onto the passers reserved floor. To remedy the stalling, bucking and rough riding condition, a major tune-up was done. That seemed to remedy the problem (Invoice #709) The mechanic informed me that an AMC dealer would have to replace the heater core.

On September 17, 1983, I again brought my car to Branford Exxon. From my last visit on Fuly 13, 1983 (32,000 miles) to this visit (34,000 miles) my car used two quarts of oil. The same problems (and to the same degree) that existed in January, 1983, were recurring. To remedy the condition, an oil sender unit was re-

placed. The car ran better but it would still stall and run roughly in cold, damp and rainy weather.

On October 17, 1983, I brought my car into ANC Falvey's Car Sales in New London, Connecticut. A loud clanking sound occurred as I started my car. Immediately upon hearing the noise I turned off the ignition. I telephoned Falvey's to find out if driving the car in this condition to their garage would cause irreparable damage and if my safety would be in jeopardy. Upon their advice I walked to their sister company (Ocean Avenue, New London) and had one of the mechanics check the car. I was advised to drive slowly to Falvey's Car Sales (10 minutes away).

Upon examination of the problem, the mechanic found that two (2) push rods had broken. He advised me that in addition to replacing the rods, I should have the rocker arms replaced (Invoice R12341)

On November 30, 1983, another noise developed. I took the car into the Branford Exxon Station. The mechanic examined the condition and determined that a connecting rod was going. He advised me to sell the car. I asked him if this was an unusual condition, given the age and mileage of the car (3 years; 36,901 miles) He stated that it was an unusual condition.

Even had I decided to sell the car, which in all good conscience I would not do, the decision was made for me. On December 9, 1983, the connecting rod broke.

To reiterate, from the first 5000 miles to the time that the connecting rod broke, the car stalled, bucked and ran roughly in cold, damp, or rainy weather varying only in degree.

I am sure that you will agree that the reliability record of this 1980 American Motors Spirit is extremely poor. And, that the service accorded me by Al Maculaitis of Al Mac Motors was extremely inefficient, let alone that his manner was totally unprofessional.

My experience with this vehicle has been thoroughly exasperating. Not only was my safety in jeopardy at times, but the safety of my passengers as well. For these reasons and for the time, energy and money expended in attempts to have a vehicle on which I could depend, I want American Motors to purchase my car for the original purchase price of \$5,602.25 (\$5503.75 plus rust preventative and undercoating \$98.50.



I have sent letters and copies of this report to Connecticut Attorney Ceneral Joseph Lieberman; Connecticut Congressman Bruce Morrison; Ralph Nader, Consumer Advocate; Mary Heslin, Department of Consumer Protection, Mike Boguslowski, Consumer Advocate - Action News 8, WTML-TV: Office of Consumer Affairs, Washington, D.C. the National Highway Traffic Safety Administration; Rhoda H. Karpatkin, Executive Director, Consumers Union of U.S., Inc. Paulette Hotton, President, Better Business Bureau and Richard D. Meck, EVP, Connecticut Automotive Trade Association. If I do not receive a satisfactory response by February 20, 1983, I shall put into effect any action necessary to have this matter rectified.

Sincerely.

Donna on funtino

Donna Infantino

Enclosures: ITEM II - COMPLAINT AGAINST MOTOR VEHICLE SALES OR SERVICE BUSINESS FIRM (Pages 1 and 2)

ITEM III - Itemized list of invoices, dates, mileage and costs

ITEM IV - Auto Repair Shops; names, addresses and telephone numbers

Copies of invoices - No. 7177 9128, R11152, No. 38340, R12833, R14789, R15533, Autosense - computer vehicle revort, No. 709, No. 194374, No. 45729, and

cc: Attorney General Joseph Lieberman
Congressman Bruce Morrison
Ralph Nader, Consumer Advocate
Mary Heslin, Department of Consumer Protection
Mike Boguslowski, Consumer Advocate - Action News 8, WTNH-TV
Office of Consumer Affairs, Waslington, D.C.
National Highway Traffic Safety Administration
Rhoda H. Karpatkin, Executive Director, Consumers Union
Paulette Hotton, President, Better Business Bureau
Richard D. Meek, EVP, Connecticut Automotive Trade Association



JAN -6 1983 OWNER SERVICES 1-82

G T61. " 8348047 1AMBA4353CK 107681

DEAR MR. PRESIDENT AMC/Jeep

I PURCHASED ONE OF YOUR AMC SPIRITS MAY 24, 1982 AND HAVE BEEN PLAGUED WITH PROBLEMS WITH IT ALMOST FROM THE VERY FIRST DAY.

I WILL TRY AND LIST THE PROBLEMS AND SEND YOU A PHOTOSTATIC COPY OF ALL RECEIPTS I HAVE ON HAND.

PLEASE LET ME KNOW IF THESE AREN'T THE PROBLEMS A USED CAR BUYER ENCOUNTERS_

I NEED SOME SORT OF SATISFACTION GIVEN TO ME AND KNOW I CAN'T EXPECT TO GET IT AT THE LOCAL DEALER AS THEY COME JUST SHORT OF REPUSING A LOAM CAR WHEN MY CAR IS IN FOR REPAIRS. THE EXCUSE BEING GIVEN IS THAT WERE SORRY WE DON'T HAVE ONE ON

NAND RIGHT NOW BUT WE CAN HAVE SOMEONE TAKE YOU HOME. WESE ARE THINGS LISTED IN THE WARRANTY BOOKLET AND IF THESE FACKISES CAN'T BE WET THEY SHOULD BE DELETED PROM YOUR WARRANTY.

CHERE IS A LIST OF THE PROBLEMS:

595 MILES: /. PAINT HAD TO BE TOUCHED UP:ON HOOD WHERE POSSIBLE BATTERY ACID HAD BEEN SPILLED AND WENT UNNOTICED ACCORDING TO SERVICE MANAGER AT THAT TIME. 2. ENGINE WAS ALSO DIESELING.

3.876 MILES: AVALVE COVER GASKET HAD TO BE REPLACED. 2 ENGINE DIESELING AGAIN.

4.772 MILES: / DIFFERENTIAL LEAK.

2. SHOCK ASSORBERS REPLACED ON HATCH. 3. TRANSMISSION LINKAGE HAD TO BE ADJUSTED. 4. WINDOWS RATTLED.

S. EMERGENCY BRAKE HANDLE WAS STICKING.

6, ENTINE DIESELING AGAIN.

3 MASTER CYLINDER 5381 MILES: A EXHAUST LEAK. 2, TRANSMISSION HOUSING LEAKING. 3.152 MILES

/. WATER LEAK IN BACK WINDOW. GIVING POOR GAS MILEAGE. 3. SCRAPING NOISE IN RIGHT SIDE.

THE PIRST WEEK I OWNED MY AMC I HEARD THIS MOISE WHICH SOUNDED LIKE A FEAT TIREMAND AND IT TURNED OUT TO BE 4 WHEELS WITH LOOSE LUG MUTS WHICH WAS BLAMED ONTO THIEVES BY THE ALAMO AMC PEOPLE.

MY THEORY IS THAT THE LUG NUTS WERE LEFT UNSECURE WHEN I PURCHASED THE CAR AND IN THE DEAL THEY EXCHANGED 4 SPORTY RIKS FOR 4 CHEAPER RIMS.

I AM VERY DISAPPOINTED IN THIS VEHICLE AND AS A FORMER FOREIGN AUTO CAMER AND A SET SPIED ONE I WILL BE WAITING FOR YOUR COURTEOUS ROPLY.

LAMB MY3 OXCT 11948?

Heral Of Smith

LL DEDEVENAERDER

Pitts 31 4. PHINER SERVILLE Parch 17, 1983 American Motors Corp. 14250 Plymouth Road Detroit, Michigan 48232 Attn: Owner Relations Dear Sirs I purchased a 1982 AMC Spirit on April 29, 1982 and have had problems since that day. I was assured by the salesman (Jerry Wolfson) and the Dealer (Northview Sptors Inc.), that they would take care of any complaints. I have found out that this is not true or else they discriminate because I am a woman alone. I have been driving for over 35 years and I can tell when my car does not perform as it should. One week after I picked up my car, I couldn't get it started and had to have it towed to the dealer. They determined that it was the starter. Why was this problem not taken care of before delivery of the car? I am still waiting for a fly wheel. I have also complained about an oil leak. My garage floor has oil spots on it as yet. The service department supposedly resealed the Rocker Cover. If so, why is my car still losing oil? As you can see by copies of my service invoices that I have paid for most of the services. They were not even courteous to me. I work for a living and my time is valuable too. I always wanted to own an American made car, and have always paid cash for my cars, but I must say that I am very disappointed with this car, the dealer, the salesman and also the service. I intend to write to the editor of the Pittsburgh Press and have him publish my letter. Mrs. Rosalia Wojciak 30171; Paulowna Street Pittsburgh, PA 15219 Phone No. (412) 681-8533 1982 ATC Spirit 2 Dr. Color: Blus: !fileage 10. Serial No. 1AMBA4350CK128505 License No. R84831 Copies of Bills Attached.

1	ľ		CASH SALES	The state of the s	Saut 1101	
i	1	i	200		EXCISE TAR	Α
				15237, 3-3	- 1	1
	1			4771 McKnight Rd.	A GREASE	TOTAL OIL & GREASE
7	14.	1	AND PART	NORTHVIEW MOTORS Inc.		
-	1	ŀ	ELS A OR			CAGNE OF
_	Ł	-	ă			
7	4		NUSTRACOF	ompletely Satisfied		
	L		ALET MECH	our Job		i trans
	-4		PALLS VCCCR SCOOL SHOP	Our Service Representative, Mr.	00	
_	1	1	THOSE BOOK SHOP			
Į	31.	-	C) BOW RECHTMENT	c.		
	i	Æ	DESCRIPTION	ILION AIN HELL		
	Ŀ	101/4			TOTAL PARTS	
ŗ	1		1/13 283	1		
	1	1	ŀ	und Chumber		
?	†	1		Mise		
	1	*	mount one	(B) WONT STAIN SOMETIMES + C		
<u> </u>	1	1	.]			
_	-					
	L			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
~	L					
	1	1		i .	3 4	1
_	\pm			Mosel Cooker Cover	12/1/1/ 11/19/	7 182518
	+	+		A Chick and such	BPECIFIED OTHERWISE	Yd hTV
_	1			C COOR METHODICAL	DESCRIPTION NOTIVEDESO	OH 1974
_	1		LJ corness /	Mostly Market	08:35 201/894-83	435 0813
_				ectnomisaged on the car of truck to secure the amount of (spains travers	A NO. I POLICE INC.	DAMES TO SECURE
_		All leganistic contractions		nedatany masera, and remay give: You wish you have a season as to consider the early considerable of the street, highways or elementers for operate the car or inch hereby the gurpose of testing and/or finapection. An express mechanics him is hereby the gurpose of testing and/or finapection. An express mechanics him is hereby	05 21590 CT CO	MBA4350CK128505
_	-	4771 McKnight Road	ÇS -	CASE OF THE THEFT OR ANY OTHER CASES BETTOND OUR CONTROL. I hareby authorite the repair work hereinather set forth to be stone along with the	1533 4 26 82	0 0000 681 8533
_	. p	MOTORS inc.	Ē	TICK PLAN - LIMITED WARRANTY, SEE REVERSE SIDE FOR TICK OF WARRANTY AND HISTOLICUS. AND MINISTER SIDE FOR THE CASE OF	ا ا	h. r Pa
	_	NO STOREM	10	TOTAL OF THE EXCLUSIVE SERVICE PROTECT		17 1/2 Paudowana
_	*	30	1		,	200
_	٠.		41.0			icial Bossiis
	1	7	100	ANYS PS-381A	128505	505821280 C. E8 91.1
	1	7	1	From D Rear D LW D RW D L. Front D R. Front D L. Side D R. Side D.		NOTICED BODY DAMAGE:
٠. ا	į				Late Character Control of the Contro	مستقط بالتعالب بطريعا
					3	
						\ : :



MAR 11 1983

WHER SERVICES

rerican Motors Sales Corp. 250 Plymouth Road troit Mi_A8232 3 - 8 - 83

Dear Sir:-

T took delivery of one of your Pacer cars 3 - 28 - 80.0n 2 - 9 -T took the car back because the speedometer stopped working. The service department found the cable broken and had to order a cable on 2-26-81 I took the car back for the new cable. They installed it. On 3-12-81 I took it back for a leak (oil on my drive). They said it was a transmission leak. The bill says they put in actrans, speedometer #0" ring.On 5-29-81 I took it back for a transmission leak sgain. They resealed the valve cover. On 7-16-81 I took it back for a leak sgain, and the pulley on the A/C system was groaning and kept kicking on & off. They lubricated the bearing and said that I would have to put arnew pulley. They charged me \$11.00. (I missed one on 6-30--81 and I'll gut it in here on 6-30-81 it was taken back for an oil leak and the bill says it was the valve cover again. On 2-25-62 it went back again for installation of the A/C pulley. On the bill it says that they pack again for mistaliation of the A/L Philey, of the bill it says that they also performed a 10,000 mi. checkup. If cost me 2:69.17.0n the bill it had written across the bill "Valve cover leaks". By this time I was so frustrated I decided to keep adding oil and drive it till it blew up. My drive began to look like some one struck oil there so I decided to get a cork gasket and put it in myself. That I did. That didnt hold either, so on3-4-83 I took it hack to Recker Motors and had a round with him about the rotten service but he said the warranty had run out and he couldn't do me any good. Said I could pay him for fixing it and send my complaint to American Motors so I aid them to fix it and it cost me \$67.02. They found that the Valve cover s warped bad.

My contention is that anything that started before the warranty ran out should be guaranteed even after the warranty rans out. I have been a buyer of American Motors products since 1956. If this complaint is not resolved better than in the past I guarantee you that you have lost a customer. I like your cars but your warranty is not carried out fairly if that kind of service exists. I have two A/M cars at present. I Pacer & I Concord) so this complaint will decide whether I buy another A.M.car. I have all the bills of the respective dates claimed here. I will get rid of them and try some other brane. F. ractory resolving of this complaint will satisfy me and I will con contain the containt will satisfy me and I will con contain the containt will satisfy me and I will con contain the containt will satisfy me and I will con contain the containt will satisfy me and I will con contain the containt will real that they should have checked to long before this. I'm not sure if the trouble is found yet, but if the crows warped it could be over.

If you require the bills, I will send them if you notify me.

Sincerely ,

Ray C Caks 1521 Darst Ave Dayton, Ohio. 45403

ID#A0A665c140290 Delivery date-3-20-8-

WKE94

Wesi.

WHER SERVICES 5 July 1986 President American Motors Corpora 14250 Plymouth Road Detroit, Michigan 48232 Dear Sir. This is the second letter concerning my 1984 Jeep Waconner Foologure A (with its enclosures) is a copy of the first letter which was sent to your Owners Relations Department. I did not get a reply or even an acknowledgement of receipt. Enclosure B is my latest bill for almost 5400 OO All I expect is a vechicle that works correctly and doesn't leak nil As soon as I got back to Texas I took the jeep back to the dealer from whom I purchased it. Not only did I want the power window unit in the front right door and the rear wiper and washer fixed, but yes another oil leak needed to be re-paired. Well, at least I got from Maryland to Texas before it started -- please note that only 2500 miles and 62 days had passed. The ves. I noticed a guddle of oil under the ieen today. I am caucht in a position where I can't help mysolf. Of course your dealers don't honor each other's work and when I am in the Army. I can't help but move when they say to; therefore I can't continue with one location. Please help me. Sincerely. Ronald M. Bishop CE. Jeep Corp - Owner Relations 4522 Briargrove Ritter Nissan LTD San Antonio, Texas 78217 (512) 650 - 0481 Ancra Motor Co U.S. Consummer Protection Agy Texas Motor Vehicle Commission Consummer Reports EMSC Zone Pallas

Dear Madam or Sir:

In February 1984 I purchased a new jeep wagoneer (SN 1JCWB7555FD177681) and have been pleased for the most part. I am a strong believer in preventive maintence and take excellent care of my property. Shortly after purchasing the jeep I moved from San Antonio to the Washington D.C. area and found that the dealers really weren't interested in servicing the jeep because I didn't buy it from them. That, however, is not why I am writing.

On May 23, 1984 I took the jeep in to have the rear wiper and washer repaired. It worked for approximately six months then they stopped.

In April 1985 the passenger side power window quit working. I took the door panel off and found that if you tapped the power unit it worked. It worked for about 6 weeks and it stopped. Again, I got it working for about 2 weeks and it has again stopped.

In September 1985 I noticed that the paint on the rear lift door was starting to pull away from the door and flake off. It is occurring where the stripe is and on the concave curve. I took it to the dealer and was told that he would get ahold of the district representative and would let me know. I received no calls. I went back and was told that I would have to get an appointent with the district representative but it would not be anytime soon. I was again given the run around. The tail gate paint is not sticking. It does not sit out in the weather. It is garaged as well as washed every week and waxed every two months — yes, both summer and winter. Isn't a paint job suppose to last longer than 18 months?

On 28 April 1986 I took the jeep in for an oil leak and was told that the rear main oil seal was bad and that toil was also leaking from the left valve cover. Of course I had them both repaired, (see enclosed bill) As I previously mentioned, the jeep has had good care. I change the oil and filter every 2-2500 miles. It has never been taken off the road and is not in the least way abused. Is an engine rear main seal only expected to last \$33,500 miles? (NOTE: When I picked up the jeep the a/c didn't blow out of the vents because a vacuum line was forgotten to be reconnected. Also, as soon as I got home I noticed oil pouring out of the bottom. I mimmediately took it back to the dealer and they replaced the rear main seal again. I was told that the first one didn't "seat' properly ????) (see second enclosed bill)



I am moving back to San Antonio next month and will take the jeep back to the dealer I bought it from, but would like to take a response from you with me.

Would you please help me?

Yes, I like the jeep but I am beginning to think I got a lemon.

Sincérely,

Ronald M. Bishop 13100 Venango Road Fort Washington, Maryland 20744

Fort Washington, Maryland 2074 (301) 292-5333

3017 272-2333

OCT ! 1 1984		- 1
AMCIJOPER Record Continuous continuous Continuous continuous	take a copy for zone life.	
10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	K.D. of Gods.	

3/25/86

George Fyrer 46 Wagon Wheel Rd Dracut Mass 01826 (617) 957-2772

(VIN) ITC WB 755 IETO 37371

Mr. George De Orio,

I am sorry that we have getten off to such a bad start.

I wrote to you last month and recieved no reply. Today 3/24/86 I

phoned your office and asked to speak to you, but your sec. without

thousing ony tacts told me you do not deal with austomer's She then

proceeded to insult no wich a burge of greations, like howdere I

call the zone office.

Mr. De Oile I am a policit person but I am wein out. I purchase a Jeep Ungener brand new Fort 1984 since then I muse dealt with four service managers at Berlin MRC one at Muirhead Inc, one at Wilmington Teep. I have close with MacOnty, No. Bird and Mr. Hoghins. I have seen it have apart in a buly shop to repair a maje. water leak. The entire tear and was replected on a recall. The major problem on oil leak in the rear main seal has all ibrhed to the which king taxed in twice to the diver, my self and my family being stranded on the side of an intersute highway in below zero weether. The original engine had three of four sea put in it before they replaced the crank them a new short block and a new could and them more sould the crank them a new short block and a new could and them more sould put or miles on it and returned it tecking of 1. Then kevin took it equin this time under anders from Misinf and Mr Hoghins. Begain 17 was year this time under anders from Misinf and Mr Hoghins. Begain 17 was year how weeks but it didn's stall leaking for about I months. With the weeks but it didn's stall leaking for about I menths. With the stalk back to Huir krad over 40 mins from my home and waited five were years back to Huir krad over 40 mins from my home and waited five were years back to Huir krad over 40 mins from my home and waited five were years back to Huir krad over 40 mins from my home and waited five were years.



Fot an appointment, they tightered the will cours and and his It out It is currently leaking worse than ever So hate we are two and one half years later I still have the same oil teak. The thouc paragraph doesn't begin to expense my frustration and over 250 daysin service I am writing to you for some help in coming to a solution, this is not a fictitious cattle its a viable oil lask I am not making it up. Your own service people tell me "Of the Stipulle line Stituk" and the 86 have been pretty good! If I don't hear from you my only conclusion will be that @ American Motore isn't interested and @ they can't service there vehicles. It De Orio I would be more than happy to meet with you at any dealer in my vicinity as long as you give me some motice. If, wife is generally home by 3:00 in the attention and I am usually home by Thank you, Surger Types

November 20, 1984

Central Office American Motors Sales Corp. 14250 Plymouth Road Detroit. Nichigan 48232

Dear Owner Relations.

I am presently the owner of a 1984 Jeep Wagoneer Ltd. I.D.# LJCW7563FT044165.

I have owned both a 1979 and a 1980 Cherokee Chief and Wasoneer Limited respectively.

I regret having to write this letter of dissatisfaction with my new Jeep.

The problem I am experiencing is a rear main seal leak which occurred at 2,700 miles. On numerous occasions the rear main seal has been replaced. The rocker arm cover gaskets on both sides were replaced.

I still had an oil leak. In addition to an oil leak, I had a transfer case leak at the input shaft seal. I then notified the Atlanta Regional Office in September. Mr. Ron Poshe at Atlanta authorized a new crank shaft and the transfer case leak to be corrected.

After the work was completed. I still had the same two leaks.

Early in October Mr. Foshe again authorized a short engine block to be put into the car. Also & this time I had a problem with one of the horns not work g and the radio which was full of static.

The radio, as a point of information, was taken out of the car twice. On one of the occasions, I was without a radio for two and a half months $(2^{\circ}1/2)$ The radio was sent to Atlanta for repairs.

000302

After all the repairs, the inconvenience, the aggravation and the wasted expense. I still have an oil leak, transfer case leak, a horn with the wrong tone, a horn pad that's dead in certain spots and a static radio.

In addition the following have recently appeared:

- Starter is very whinny.
- Engine has a miss in it.
 Floor mats are not holding up.

The Atlanta office has tried to correct these problems but has failed. It appears that it is now back in your hands in the Central Office to clear up all the above mentioned defects. I would also like to call your attention to my need for a loaner while my car is in service.

Your attention to this matter is imperative at this point in time

Sinterely.

Harvey Hazan 1561 S.W. 67 Terrance Plantation, Florida 33136 305 791-3087 Bus 756-1613

HH/ah

cc: Mr. Gary Cohen, Attorney



WIMER SERVICES

Mullen . Nebraska July - 12th - 1986 :

MSC ZCNE CFF : Dear Sira:: __

Inclosed is a repair on my Jeep Wagon that should not have been Resided

if there had of been a proper V/C Gaskets in stalled in the first

place. I have had Four of your Cars in the last Twelve Years two were very . Satisfactory but the last Two here gave me un nessary.

Trouble on account of Oil lekage around the Value Covers A Four Masel drive Eagle and The Jeep Wagoneer Bought June - 26 - 1984 it first Leaked anti Freeze around the hoses the first three Konthe sina

a little Cil around the Valve Covers in air months but the Dealer

Dolan Berg Motors, 119 Nest Sth - For a Platte Nebracks did nothing about it when they serviced the car said it almos amount to say.....

Trouble, as it kept getting worse I still thought it was mostly the the Anti Freeze that I was smelling . But it turned out to be the Cil.

Lea kage instead - So even the the to of the Marranty has expired That the Esnefactory or American Sotors Company should Pay He for

this Repair bill for if the proper Gaskets had been installed in the first place this bill would not of been Nessary at all in both of

the last Two Cars that I Purchased And I assure You that it thisis not Corrected that I Will mever Purchase another of your Carain

If You can give me some just Reason why the last Two Gars I Bought-Have had the Same Oil Problems I would Like to Hear it ::

Do Not just throw this in the Wast Basket I expect to hear from You ;;

Noise-



L & L SALES & SERVICE Carlson Building MULLEN, NEBRASKA 69152 Prane 546-2851

	S ORDER NO.				7/	10/86	
-COMESS	MER	LE_		R. YM			
	984		هرء	57	7.10	lacar.	
10	CWE	7539E	7119	255	9	D551	8
80LD 81	CASH C	OD. CHARGE	OH ASCT.	MOSE METO	PALD OUT	milag	•
ary.	'	DESCRIPT		'	PRICE	* "	MT.
/_	153	9.772	U/a_	Guskl	75_	8	===
							├
	11.11	2	121				
	75.44	20	_QRJV 2- u = 2	12			
	COVE	~	הכח. 3.	211		51	20
		<u> </u>					<u> </u>
	$\perp P$	<u>/_</u>		~	}		وا
	—	Thur	L-4	ZJ#.	<u>u</u>		<u>_</u>
		f from	<u>~</u>				بيجا
					TAX		00
RECEIVED BY	·					400	47
ı					TOTAL	50	2/

All claims and returned goods MUST be accompanied by this bill. PRODUCT 610

4174

Thank You

PATRICK MICHAEL DECHARLES
70 HUDSON AVE
TOTOWA, NEW JERSEY 07512
4 SEPTEMBER 1985

AMC/JEEP/RENAULT POST OFFICE BOX TOLEDO, OHIO 43699-9980 però

DEAR SIR:

FOR THE PAST THINTEEN (1. YEARC, I HAVE OWNED A FOREIGN MADE 4X4 VEHICLE TITH EXCELLENT RESULTS. IN JULY OF 1984, I DECIDED TO TRY A DOMESTIC MADE 4X4 VEHICLE AND BY ANNIHAM. A LITTLE OVER 15,000 MILES LATER I HAVE FOUND THAT TO BE A BIG MISSAGE

I BOUGHT ONE OF YOUR AWARD WINNING CHEROKEE CHIEF VEHICLE WITH A MAJOR ENGINEERING DEFECT WITH THE CRANKSHAFT ASCEMBLY IN THE FOR A 1.2.6 LITER ENGINE, I HAVE NOT BEST ABLE TO USE THE VEHICLE FOR A MANTH. WHEN THE LEAKAGE OF OIL WAS FIRST NOTICED FROM THE UNDERSIDE OF THE VEHICLE I TOOK THE VEHICLE OF THE NEAREST DEALER AND ASKED TO HAVE THE LEAK CHEKKE WITH PARTICULAR ATTENTION THE PROPERTY OF THE BEAR KAIN ENGINE OIL SEAL AND THE JUL PAR SEAL, FROM MY INSPECTION OF THE WASHE OF THE PARTICULAR ATTENTION TO CREDITED WHAT I ASKED FOR BUT I PARTICULAR HET DEALER ENVER CHECKED WITH PARTICULAR HET MATERIAL OF THE PARTICULAR HET MADERS OF THE WALLE OF THE DEALER HOVER GASKETS AS KOTED II ENCLOSURE!

THE VEHICLE STILL LEAKED ABOUT SQUART OF OIL EVERT 80 MILES. I TOOK IT BACK TO THE DEALER AND WAS THEN TOLD ABOUT THE EMGINEERING DEFFERT. THE DEALER FOR ORDER THE PARTS AND IT TOOK 21 DAYS TO FIND THE FOR THE DEALER FOR SHEDULE THE TWO DAY OPERATION OF CHANGING COUT THE CRANCELAFT. MEANWHILE THE DEALER CHANGED MY OIL BE SCHEDULED THE TWO THE PARTS CAME IN AND I COULD USE IT UNTIL THE PARTS CAME IN AND I COULD USE IT UNTIL THE PARTS CAME IN AND I COULD VEHICLE LEAKING THAN FORCE AND THE PARTS CAME IN AND I COULD VEHICLE LEAKING THAN FORCE OF THE VEHICLE AND THE PARTS CAME IN AND I COULD VEHICLE LEAKING THAN FORCE OF THE WEIGHT AND THE PARTS CAME IN ANY OF THE PARTS CAME IN THE PARTS C

FROM 30 JULY 1925, TO THE PRESENT, I HAVE NOT USED THE VEHICLE EXCEPT FOR DRIVING IT BLOK TO THE DEALER ON 21 AUGUST 1985, TO HAVE THE CREMISHET REPLACED. THE WORK IS STILL NOT COMPLETED BECAUSE THE DEALER BROKE TWO COMPLETING FOD BOINS IN THE PROCESS. REPLACEMENT BOINS COULD NOT BE FOUND IN THE LOCAL AREA.

